

Hatebur AMP30

Machine No. 430065

Maintenance History

- **1982** Upgrade Ejector cam to 70mm (stroke)
- **1992** Part-rebuilt Transfer Unit
- **1999** Induction Heater: Replace original Generators with new Inverter.
- **2000** Part-rebuilt and upgrade machine
 - Upgrade to 140 U/min
 - Repair Shear housing (Insert)
 - Replace Pneumatic System with new (Festo)
 - Part Up-grade Lubrication System
 - Replace Electric System complete with new
 - Replace ESA control with new (PLC based)
 - Replace Bar rack with new
- **2015** Replace Shear cam and Shear Lever with new
- **2018** Repair upper Feed shafts

09.04.2025

Ernst Schneeberger